Work Order ID 57057 Page 1 March 18, 2010 11:36:13 AM Setup Accept Start Item ID: DSI 9505-012 Revision ID: Stop Item Name: Basket Conversion Installation, RH Start Qty: 2.00 Start Date: 3/18/10 Cust Item ID: Req'd Qty: 2.00 Required Date: 3/19/10 Customer: Reference: Run Start Tooling: Date: Date: Process Plan: Approvals: Stop SPC (Y/N): Date: QC: Date: Reject Reject Insp. Draw Accept Draw Plan Sequence ID/ Operation Set Up/ Qty Qty Number Stamp Code Number Rev. Work Center ID Description **Run Hours Revision Nbr** Draw Nbr 0.00 100 0.00 Memo Photocopy bluefile &type labels per PPP DSI9505-012 Document Control Pick Kit 0.00 110 0.00 Packaging Memo Packaging QC4-100% Inspect kits for completeness 120

QC

Quality Control

Memo

	<i>h</i>	
	1 77 2	
the same of the sa		

Dart Aerospace Ltd

W/O: ,		WORK ORDER CHANGES					L CALL
DATE	STEP	DS19505-011 PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
10/3/15	100	Remail D 2258-300 (Lable) From who + Bom. Pre installa on 103713-041/042.	W	10.03.15	i	100519	8
	1 Mar	ADD copy of new Bom Im led. ? Add DSI lw. A & the dwy box perm housef					

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:	
Resolution:		Disposition:	QA: N/C Closed:	Date:	

NCR:			CE (NCR)					
		Description of NC		Corrective Action Section E	3	Verification	Annyoval	Annuaral
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

100	

Work Order ID 57057

Merch 18, 2010 11:36:14 AM



Page 2

Item ID:

DSI 9505-012

Accept

Revision ID:

Item Name:

Basket Conversion Installation, RH

Start Date:

3/18/10

QC:

Start Qty: 2.00

Required Date: 3/19/10

Req'd Qty: 2.00



Draw

Number

Cust Item ID: Customer:

Reference: Approvals:

Process Plan:

Operation

Description

Date:

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Draw

Rev.

Plan

Code

Reject

Qty

Setup Start



Sequence ID/

Work Center ID

130

Packaging Packaging

Memo

0.00

0.00

Location:

140

Quality Control

Identify and pack for shipping as per PPP DSI9505-012

PPP rev:

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Run

Accept

Qty.

Start

Stop

Stop

Reject Insp.

Number Stamp

CX10/3/19

•	2	

. Picklist Print

March 18, 2010 11:36:11 AM

Work Order ID: 57057

Parent Item: DSI 9505-012

Parent Item Name: Basket Conversion Installation, RH

Comments:	IPP Rev:A new iss label DD 10.03.18	sue DD 10.03.01	verifie	ed by:JLM	IPP Re	v:B add			tart Date: 3/18 Start Qty: 2.00		Required Date: 3 Required Qty: 2	
Component Item ID/ Item Name AN3-11A	Replacement Item ID	Mfg/ Purch Purchased	Bin Item No	Primary Location	Last Location	Route Seq ID 110	Unit of Measure Each	Qty on Hand 250.0000		Qty Issued	Date Issued	Status
				Warehoo Loca Main Wa	ation	Loc	<u>Qtv</u>	Loc Code				
				ST35			250 29 170		ta	}		
AN4-20A (3) Bolt		Purchased	No		14820	110	51 Each	766.0000	6,0000	5-3-19	Je	
60.017.0				Warehou Loca Main Wa	tion	Loc (<u>Oty</u>	Loc Code				

QS1 OT SP

14 SIN9 00363-

Purchased

Purchased

No

AN960JD416 40 Washer MASINADO4637

QSI 617 SP

Main Warehouse ST359 766 104016 703 63 110 Each 0.0000

Each

110

M113788 10-3-1959 M113706 10-3-1950

XC

ALTERNATION AND AND		
· 并:		

Picklist Print

March 18, 2010 11:36:11 AM

Page 2

Work Order ID: 57057

Parent Item:

DSI 9505-012

Parent Item Name:

Basket Conversion Installation, RH

Comments:

IPP Rev:A new issue DD 10.03.01 verified by:JLM

label DD 10.03.18 verified by:JLM

IPP Rev:B add

Start Date: 3/18/10

Start Qty: 2.00

Required Date: 3/19/10

Required Qty: 2.00

Component Item ID/ Item Name

D2258-300

Lid Assembly

Bushing

Label

Replacement Mfg/ Item ID

Purch Manufactured

Manufactured

Manufactured

No

Bin Primary Item Location

Last Location

Route Seq ID 110

Unit of Measure Each

Qty on Hand 11.0000

Loc Code

Remaining Qty Qty To Pick Issued 2,0000

Date Issued

Status

no collection,

D3713-042 B 56576 Warehouse
B 56 58 | Main Warehouse

ST505

42011 55718

2 9 110 Each

Loc Qty

11

0.0000

110 Each

Loc Qty

28.0000

Loc Code

12,0000

10-3-19 5

Warehouse Location Main Warehouse ST086 38229

48627

28 7 21

	×			
	gi			
15 6 6				
100				

Picklist Print

March 18, 2010 11:36:11 AM

Page 3

Work Order ID: 57057

Parent Item:

DSI 9505-012

Parent Item Name: Basket Conversion Installation, RH

Comments:

IPP Rev:A new issue DD 10.03.01 verified by:JLM

label DD 10.03.18 verified by:JLM



IPP Rev:B add

Start Date: 3/18/10 Start Oty: 2.00

Required Date: 3/19/10

Required Oty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch Manufactured

Primary Item Location No

Last Location

Warehouse

Location

Route Seq ID 110

Unit of Oty on Measure Hand Each 24.0000

Remaining Oty To Pick Issued 4.0000

Qty

Date Issued

Status

D3725-1

I Hoop

Manufactured

Manufactured

Main Warehouse ST086 45575 50939 51118 110

Loc Qty Loc Code 24 15 Each 15,0000 6,0000







	Warehouse	Lo	oc Qty	Loc Code
	Location	-		Bot Cour
	Main Warehouse			
	ST		15	
	46894		15	
No		110	Each	13.0000

Warehouse Location	Loc Qty	Loc Code
Main Warehouse		
ST515	13	
51119	13	

	25.	
٠		
• .		

Picklist Print

March 18, 2010 11:36:12 AM

Work Order ID: 57057

Parent Item:

DSI 9505-012

Parent Item Name: Basket Conversion Installation, RH

Comments:

IPP Rev:A new issue DD 10.03.01 verified by:JLM

label DD 10.03.18 verified by:JLM



IPP Rev:B add

Start Date: 3/18/10

Start Qty: 2.00

Required Date: 3/19/10

Required Qty: 2.00

Component Item ID/

Item Name MS21042L3 Replacement Mfg/ Item ID

Purch Purchased

Primary Item Location No

Last Location

Route Seq ID 110

Unit of Measure Each

Qty on Hand 2,167.000 12.0000

Loc Code

Remaining Qty To Pick Issued

Qty

10-3-19

Date Issued Status

Purchased

Warehouse Loc Qty

Location Main Warehouse

> ST300 2167 110844 35 111274 27 111668 58 112314 285 112385 42

113537 113644

113523

1000 Each

20

700

2,263.000 6.0000

10-3-19 50

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST300	2263	
102552	6	
104248	6	
110507	184	
111827	113	
113422	954	
114108	1000	

110

March	18	2010	11.26.12	4.8

		100	
The state of			
field that is			

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D205-541 REV. G & INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D205-541 REV. 2
REF. TCCA STC SH96-120, FAA STC SR00696NY & EASA STC EASA.IM.R.S.01242

Purpose:

To provide the parts and instructions for converting a D205-541-043/-044 basket to a D205-541-045/-046 basket.

Parts List:

Qty -011	Qty -012	Part Number	Description
X		DSI 9505-011	Basket Conversion Kit, LH
_	X	DSI 9505-012	Basket Conversion Kit, RH
1		D3713-041	Lid Assembly, LH
	1	D3713-042	Lid Assembly, RH
3	3	D3748-1	Hinge Half
2	2	D3725-1	Ноор
2	2	D3757-1	Blanking Plate
1	1	D2258-300	Placard (Pre-installed on D3713-041/-042)
6	6	AN3-11A	Bolt
12	12	NAS1149D0363J	Washer (or AN960JD10)
6	6	MS21042L3	Nut (or MS21042-3)
3	3	AN4-20A	Bolt
6	6	NAS1149D0463J	Washer (or AN960JD416)
6	6	D3723-1	Bushing
3	3	MS21042L4	Nut (or MS21042-3)

Procedure:

- 1. Remove and retain D2332-041 Prop Arm and attaching hardware.
- 2. Remove and retain D2530 Handle, D2535 Springs, D2537 Bushings, and attaching hardware.
- 3. Separate lid from hinge on D205-541-043/-044 by removing 2 x AN4-7A bolts.
- 4. Trim existing hinge pieces flush with the top frame of the basket base as shown in Figure 1
- 5. Break tack welds between mesh and frame in top of basket base as shown in Figure 1
- 6. Cut basket down by 4.00" (102mm) per Figure 1.
- 7. Trim frame for installation of basket hoops per Figure 1.
- 8. Deburr stubs and basket base top frame.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE:
10.03.16
CERT. NO.:
SH96-120
ISSUE NO.:
3

Α	NEW ISSUE DESCRIPTION			RF	10.03.16
REV.			DESCRIPTION	BY	DATE
DESIGN DS		DS	DART AEROSPACE LTD		
DRAWN		RF	HAWKESBURY, ONTARIO	CAN	ADA
CHECKED		4	DRAWING NO.		REV. A
MFG. APPR.		N	DSI 9505	5	SHEET 1 OF 5
APPROVED 4.		4.	TITLE		SCALE
DE APPR. 10.03.16		4	MODIFIED UTILITY-BASKET NT		
		3.16	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND COMPRENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THA NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMANCATED TO ANY OTHER PERSON WITH WRITTEN PERMISSION PROM LOWAT ASSOCRACE LTD.		LTD



CETERENCE ONLY

- Install D3725-1 Hoops and stubs. Tig weld stubs and hoops to existing basket base top frame using ER316L filler rod per AWS D17.1 2001 Class "A" per Figure 2.
- Tig weld base top frame to existing basket base using ER316L filler rod per AWS D17.1 2001 Class "A" per Figure 2.
- 11. Trim mesh and tack weld every available stand to new frame.
- Locate D3713-041/-042 Lid Assembly on modified base per Figure 3 Use 0.20" (5mm) thick spacers between the lid and the modified base for proper positioning. Position 3 x D3748-1 Hinge Half on modified base and weld in place using 0.125" (3mm) thick spacers between upper and lower hinge half per Figure 3.
- 13. Transfer Ø0.257 (F drill) hinge holes in D3713-041/-042 Lid Assembly to D3748-1 Hinge Halves.
- Touch up paint on modified base per ICA-D205-541.
- Attach D3713-041/-042 Lid Assembly to modified base using AN4-20A bolts and associated hardware per Figure 4.
- 16. Install D2332-041 Prop Arm and attaching hardware per Figure 4.
- 17. Install D2530 Handle, D2535 Springs, D2537 Bushings, and attaching hardware per Figure 5.
- 18. Install D3757-1 Blanking Plates and attaching hardware per Figure 6.
- Lift and drop lid to ensure lid closes properly on modified base.
- Install a placard (not provided) next to the Product ID label to indicate "Basket has been modified to D205-541-045/-046 configuration per DSI 9505".
- If desired, the D205-541-047/-048 steps can be installed on the modified basket base per section 3.2 of D205-541 Rev. G, or later approved revision.
- Modified basket can be re-installed on the aircraft per section 3.1 of D205-541. Update Weight and Balance per section 4 of D205-541.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

BY: D. SHEPHERD (DE # 02)

DATE: 10.03.16
CERT. NO.: SH96-120
ISSUE NO.: 3

DESIGN DS
DRAWN RF
CHECKED MFG. APPR.
APPROVED DE APPR.
DATE 10.03.16

DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA

DRAWING NO. DSI 9505

SHEET 2 OF 5 SCALE

REV. A

NTS

TITLE
MODIFIED UTILITY-BASKET


COPYRIGHT © 2010 BY DART AEROSPACE LTD

BENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE DOPRESS CONDITION THAT IT IS

USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO MAY OTHER PERSON WITHOUT

WRUTTEN PERMISSION FROM DAYL ARROSPACE LTD.

HEFERENCE ONLY



TRIM TOP FRAME
AT THIS LOCATION
AND RETAIN STUBS
FWD/AFT OF
BASKET BASE

DETAIL A

FIGURE 1. - FRAME TRIM DETAIL




FIGURE 2. - HOOP WELDING DETAIL

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

BY: D. SHEPHERD (DE # 02)

DATE: 10.03.16
CERT. NO.: SH96-120
ISSUE NO.: 3

DESIGN DS		DART AEROSPACE LTD		
DRAWN	RF	HAWKESBURY, ONTARIO, O	ONTARIO, CANADA	
CHECKED	4	DRAWING NO.	REV. A	
MFG. APPR.	B	DSI 9505	SHEET3 OF 5	
APPROVED	4	TITLE	SCALE	
DE APPR.	#	MODIFIED UTILITY-BASKET	NTS	
10.03.16		COPYRIGHT @ 2010 BY DART AEROS	PACELTO	

. . The Sec

ETERENCE ONLY




FIGURE 5. - LATCH INSTALLATION




FIGURE 6. - D3757-1 BLANKING PLATE INSTALLATION

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

BY: D. SHEPHERD (DE # 02)

DATE: 10.03.16
CERT. NO.: SH96-120
ISSUE NO.: 3

DESIGN	DS	DART AEROSPAC	FITD
DRAWN	RF	HAWKESBURY, ONTARIO, O	CANADA
CHECKED	4	DRAWING NO.	REV. A
MFG. APPR.	W	DSI 9505	SHEET 5 OF 5
APPROVED	4	TITLE	SCALE
DE APPR.	#	MODIFIED UTILITY-BASKET	NTS
DATE 10.0	3.16	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PROVITE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATIED TO MY OTHER PERSON WITHOUT WRITTEN PER	